

HEIGHT GAGE

Adapter.....	05
Dial.....	05
Electronic.....	05

HOLDERS

BT40.....	27,32
CAT40.....	27-28,32-33,39,69
CAT50.....	27-28,69
End Mills.....	28
ER Collets.....	27,29,32
Face Mill.....	28,38,69
HSK63A.....	29
Indexable.....	61-62,76
Indicators.....	10
ISO40.....	27-28,69
Jacobs Taper.....	27
Morse Taper.....	27
Shell Mill.....	28,69
Universal.....	10,13
Weldon Shank.....	45

HSS

Annular cutter.....	40-44
Counterbores.....	50
Drills.....	02,41,48-49
End Mills.....	02,38-39
Keyway Broach.....	02,54
Reamers.....	41,52,53
Taps.....	51
Tool Bits.....	50

I

INDEXABLE

Boring Bar.....	02,55-56,59-60,65,76
Countersinks.....	49
End Mills.....	65-68,76
Face Mill.....	39,64,67-69,76
Groove Tool.....	62
Lathe Tool.....	57-62

INDEXING FIXTURES

5-C.....	36
Indexing Talstock Turrets.....	36
Rotary Tables.....	37

INDICATOR

Co-Axial.....	09
Dial.....	10-11
Electronic.....	03
Holder.....	10
Point Kit.....	13
Test.....	10-11

INSERT

Aluminum.....	55-58,60,62,64-67,72
Carbide.....	49,55-72

L

LATHE

Chuck.....	26
Tool Bits.....	50

LEVELS

Frame Spirit.....	18
Master Precision.....	18

LIVE CENTER

.....	34
-------	----

M

MACHINE COUNTER

.....	16
-------	----

MAGNETIC

Base.....	11,13
Chuck.....	20

Indicator Back.....	13
V-Blocks.....	17,20
Z-Axis Setter.....	09

MICROMETERS

Blade.....	07-08
Bluetooth.....	08
Depth.....	07
Digital.....	06
Disc.....	06
Electronic.....	06-08
Inside.....	07
Multi-Anvil.....	08
Outside.....	06,17
Point.....	07
Screw Thread.....	07
Stand.....	08
Three-Point Internal.....	07

MILLING MACHINES

DRO 2 Axis.....	74
DRO 3 Axis.....	75
DRO 4-Axis.....	75

MILLING STOP

.....	13
-------	----

N

NEEDLE FILES

.....	76
-------	----

NUT

ER Collets.....	29
T-Slot.....	36

P

PARALLEL

Adjustable.....	35
Steel.....	35
Thin.....	35
Wavy.....	35

PILOT PIN

.....	45
-------	----

PIN GAGE

.....	14
-------	----

PLATE

Angle.....	20
Back.....	25-26
Dividing.....	37
Sine.....	20

PROTRACTORS

.....	15
-------	----

PULL STUD

.....	28
-------	----

PUNCH

Transfer.....	34
---------------	----

Q

QUICK CHANGE TOOL POST

.....	22-24
-------	-------

QUILL STOP

.....	15
-------	----

R

R8 SHANK

Boring Head Shank.....	49
Collets.....	31
End Mill Holder.....	28
ER Collets Holder.....	27
ER Collets w/ R8 Shank Set.....	32
Lathe Chucks.....	26
Face Mills(APKT Inserts).....	65,76
Face Mills(TPG Inserts).....	65
OZ Collets w/ R8 Shank Set.....	33
R8 to Jacobs Taper Arbors.....	33
R8 to Morse Taper Adapter.....	45
Shell End Mill Adapter.....	64,69
Weldon Shank for Drill.....	45

RADIUS

Dresser.....	36
Gages.....	16

REAMERS

Aligning.....	41,53
Chucking.....	52
Set.....	52-53

ROCKWELL HARDNESS TESTER

.....	73
-------	----

ROTARY TABLE

.....	37
-------	----

RULERS

.....	15-17
-------	-------

S

SCREWS

For Indexable Boring Bar.....	55-56
For Face Mill.....	64,68-69
For Face Mills W/ APKT Inserts.....	66-67
For Indexable Turning Tool.....	56,60

SCREWDRIVER SET

.....	77
-------	----

SHORE HARDNESS TESTER

.....	16,78
-------	-------

SINE

Plates.....	20
Vises.....	19

SLEEVE

Morse Taper.....	45
------------------	----

SPANNER

Combination Wrench.....	77
Self-Setting.....	77

SQUARES

Bevel Edge.....	05
Combination.....	15
Cylindrical.....	17

STAND

Micrometer.....	08
-----------------	----

STRAIGHT EDGE

.....	15
-------	----

SURFACE ROUGHNESS TESTER

.....	34,78
-------	-------

T

T-SLOT NUT

.....	36
-------	----

TABLES

Horizontal & Vertical.....	37
----------------------------	----

TAPS

Combined Tap & Drill.....	51
NPT Taper Pipe.....	51
Sets.....	51
Spiral Flute.....	51
Spiral Point.....	51

TAPPING HEAD

.....	21
-------	----

TELESCOPING GAGE

.....	12
-------	----

THICKNESS GAUGE

.....	16,78
-------	-------

THREADING

.....	50,57-59,62
-------	-------------

TOOL BITS

.....	50
-------	----

TOOL HOLDER

.....	58,61-62,76
-------	-------------

TURNING TOOL

.....	57-62,76
-------	----------

V

V-BLOCKS

.....	17
-------	----

VICES

CNC.....	19
Doule Lock.....	19
Electrode.....	19
Milling.....	19
Screwless.....	18-19
Sine.....	19
Toolmakers.....	18-19

Z

Z-AXIS SETTER

.....	09
-------	----

ZERO SET

.....	16
-------	----