

A

ADAPTERS
 Boring Head..... 27,49
 Collet Chuck..... 27,29
 Drill Chuck..... 33
 End Mill..... 28
 Height Gauges..... 05
 Weldon..... 45

ANGLE
 Blocks..... 15,20,35
 Gage..... 16
 Plates..... 20,35

ANNULAR CUTTERS
 Carbide Tipped..... 41
 HSS..... 40-44
 Cobalt..... 41,44
 Nitto/Weldon/One-Touch Shank..... 41
 Holder..... 45

ARBOR
 Drill Chuck..... 21,33
 Jacobs Taper..... 21,33
 Morse Taper..... 21,33

AXIS SETTER, MAGNETIC..... 09

B

BACK PLATES..... 25,26

BASES-MAGNETIC..... 13

BLADE
 Cut-off..... 63

BLOCKS
 1-2-3..... 35
 2-3-4..... 35
 2-4-6..... 35
 25-50-75mm..... 35
 Angle..... 35
 Bench..... 17
 Collet..... 17,29
 Gage..... 14
 Magnetic..... 17
 Space..... 14
 Vee..... 17

BORE GAGES..... 11

BORING BAR
 Aluminum Cutting..... 55-56,60,65
 Boring Head Shank..... 49
 Carbide Tipped..... 49
 Coolant Through..... 02
 Heavy-Duty..... 55
 Indexable..... 02,55-56,59-60,65,76
 Steel Cutting..... 02,55-56,59-60,65,76

BORING HEAD..... 49

BROACH-KEYWAY..... 02,54

C

CALIPER
 Accessories..... 04
 Dial..... 04
 Electronic..... 03-04,12
 Welded Seam..... 16

CARBIDE
 Indexable End Mills..... 65-68,76
 Inserts..... 49,55-72

CAT40 / CAT50
 Holders..... 27-28,32
 Pull Studs..... 28
 Tightening Fixture..... 30

CENTER
 Drills..... 49

CHUCKS
 5C Collets..... 17,25,32
 Collet..... 27-29,32-33
 DIN..... 31
 Drills..... 33
 ER Collets..... 27-29,32
 Lathe..... 26
 Magnetic..... 20
 Nut..... 29
 R8..... 27,28,32,33,64,69

CLAMPING KITS..... 36

CNC
 End Mill..... 02,38
 Holder..... 27,28,33
 Vise..... 19

COLLETS
 5C..... 31
 E/R..... 31-32
 Expanding..... 36
 Hex..... 31
 Metric..... 31
 Morse Taper..... 31
 OZ..... 33
 R8..... 31
 Rubber Flex..... 21
 Sets..... 31-33
 Square..... 31

CONNECTION CABLE..... 03,08

COUNTERBORES
 Cap Screw..... 50
 Interchangeable Pilot..... 50

COUNTERSINK
 Set..... 49
 Weldon Shank..... 41

CUTTER
 Annular..... 40-44
 Dovetail..... 39
 Woodruff..... 39

CUT-OFF TOOLS..... 57-59,63

D

DEMAGNETIZER..... 20

DIAL
 Bore Gages..... 11
 Caliper..... 04,17
 Height Gage..... 05
 Indicator..... 10-11,13
 Protractor..... 15
 Test Indicator..... 10-11

DIAMOND TOOLS
 Files Sets..... 76
 Wheels..... 37,73

DIVIDING PLATES..... 37

DRESSERS
 Radius & Angle..... 36
 Sine..... 36

DRILL
 Chuck..... 21,33
 Sleeves..... 45

DRILLS
 1/2" Shank..... 02,48
 Center..... 49
 Countersinks..... 41,49
 Jobber Length..... 02,48
 Sets..... 02,48
 Weldon Shank..... 41

E

EDGE FINDERS..... 17

ELECTRONIC
 Angle Gage..... 15
 Bore Gages..... 11

Caliper..... 03-04,12
 Depth Gage..... 7,11
 DRO..... 08,74-75
 Height Gauges..... 05
 Indicators..... 03
 Micrometer..... 06-08
 Protractors..... 15
 Scales..... 08
 Test Indicator..... 10
 Z-Axis Setters..... 09

END MILLS
 Carbide..... 38
 Carbide Tipped..... 38
 Cobalt..... 02,38
 Corner Radius..... 39
 Finishing..... 02
 HSS..... 38-39
 Indexable..... 65-68,76
 Multi-Flute Bridgeport..... 38
 Roughing..... 38
 TiAlN Coated..... 02,38

EXPANDING ARBOR SETS..... 36

F

FACE MILLS
 High Feed..... 68
 With APKT Inserts..... 39,64,76
 With ONGX Inserts..... 69
 With R8 Shank..... 65,76
 With SPG Inserts..... 64
 With TPG Inserts..... 64

FIXTURES
 5C Spin Index..... 36
 CNC Tightening..... 30
 End Mill Grinding..... 38
 Horizontal & Vertical 5C..... 36

G

GAUGE
 Angle..... 16
 Block Sets..... 14
 Bore..... 11
 Center..... 16
 Coating Thickness..... 78
 Depth..... 11
 Pin..... 14
 Radius..... 16
 Screw Pitch..... 16
 Screw Thread..... 16
 Small Hole..... 12
 Telescoping..... 12
 Thickness..... 16
 Thread Measuring Wire..... 13
 Wire & Sheet Metal..... 16

GRINDER
 Air..... 76
 Angle..... 76
 Die..... 76
 Universal Cutter..... 76

GROOVE TOOL..... 62-63

H

HANDLE
 Pin Gage..... 14
 Quill Feed..... 15

HARDNESS TESTER..... 16,73,78

HOGGER MILLS..... 66